

## Stopbank maintenance performance measure

### Hutt River

Percentage of total stopbank length for each condition rating

Condition Rating	2007/08
1	97%
2	0%
3	0%
4	3%, Shandon, crest low

### Otaki River

Percentage of total stopbank length for each condition rating

Condition Rating	2007/08
1	100%
2	0%
3	0%
4	0%

### Waikanae River

Percentage of total stopbank length for each condition rating

Condition Rating	2007/08
1	44%
2	0%
3	0%
4	56%, JC Park, due for capital upgrade

### Guide to Condition Ratings

- 1 Meets required standard - scheduled maintenance only
- 2 Meets required standard - minor repairs required
- 3 Below required standard - specific repairs required
- 4 Below required standard - major repairs or renewal required